

DRAFTSIGHT 2025 SP4

List of Fixed IRs

IR #	Brief Description of issue(s) fixed
Annotation Issues	
IR-1395169	Annotation With dimension styles selected, dragging a dimension line causes the alternate unit text to move above the line, despite being set to display below.
IR-1395308	Annotation Chinese versions of DraftSight incorrectly enable/disable tolerance options based on the Calculation setting.
IR-1399467	Annotation Multiline Text Editor issues in 2025 SP2: unable to delete multiple lines.
IR-1408171	Annotation In DraftSight 2025, deleting a line of text in a "Note" object also deletes the second line below it.
IR-1362172	Annotation DraftSight users cannot double-click a simple note to edit it, which disrupts workflow.
Drafting Issues	
IR-1389194	Drafting Incorrect representation of LINSTYLE in DraftSight Mechanical when copied over from other 2D CAD programs.


IR #	Brief Description of issue(s) fixed
IR-1395169	Drafting Fails to create a fillet when the specified fillet radius is equal to the radius of one of the circles being filleted.
IR-1396699	Drafting Unable to select faces using UCS command in DraftSight Enterprise.
IR-1396737	Drafting DraftSight 2025 SP1 hangs and gives an incorrect "Selected entity is not a component" error when the EDITCOMPONENT command is used on a dimension.
File Operations	
IR-1418830	File DraftSight Mechanical 2025 SP2 crashes when copying and pasting a drawing between files.
IR-1406125	File DraftSight 2024 SP4 shows a "drawing file is not valid" error when opening a specific file.
IR-1401794	File In DraftSight 2025 SP2, the editing dimensions in a drawing file result in an "A dependent expression cannot be evaluated" error.
IR-1409453	File DraftSight 2024 SP4 crashes when opening files created in 2020 and stored in Enovia.
Printing Issues	
IR-1389181	Printing Print Setting Location in Options > System Options > Printing does not change.
IR-1395896	Printing The logo in the title block shifts when printing in portrait mode after upgrading to DraftSight 2023.
IR-1384468	Printing Printed DWF files from DraftSight don't reflect the specified scale, causing incorrect dimensions.
System & User Interface	
IR-1424433	System Crash occurs after switching to Model Space following use of the View Tiles Manager feature in a Layout Sheet.
IR-1424743	System Typing Korean text in the Options > System Options search box crashes DraftSight.
IR-1408398	User Interface DraftSight crashes after moving a grip cycling option and saving the changes.

IR #	Brief Description of issue(s) fixed
Blocks	
IR-1409163	Blocks Blocks sometimes fail to automatically snap to the correct rotation of an infinite line during insertion.

Dassault Systèmes is a catalyst for human progress. Since 1981, the company has pioneered virtual worlds to improve real life for consumers, patients and citizens.

With Dassault Systèmes' **3DEXPERIENCE** platform, 370 000 customers of all sizes, in all industries, can collaborate, imagine and create sustainable innovations that drive meaningful impact.

For more information, visit: www.3ds.com



3DEXPERIENCE®

Europe/Middle East/Africa
 Dassault Systèmes
 10, rue Marcel Dassault
 CS 40501
 78946 Vélizy-Villacoublay Cedex
 France

Asia-Pacific
 Dassault Systèmes
 17F, Foxconn Building,
 No. 1366, Lujiazui Ring Road
 Pilot Free Trade Zone, Shanghai 200120
 China

Americas
 Dassault Systèmes
 175 Wyman Street
 Waltham, Massachusetts
 02451-1223
 USA

**Virtual Worlds
for Real Life**

